

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20183477
Address: 416 NW MAIN ST, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Jason McRoy	Failed	Tuesday, April 09, 2019

Corrective Action Required:

- | | | | |
|---|------|----|---|
| 1 | Misc | 1. | Fire block heat flue at ceiling where pan does not cover at ceiling 1st fl |
| | | 2. | Fire stop nm electrical penetrations in mudroom north of garage entry door at top plate. |
| | | 3. | Attach bath fan in front guest bath 1st fl. |
| | | 4. | Fire stop nm electrical penetrations right of sliding glass doors 1st fl top and bottom plates. |
| | | 5. | Fire block fir down space from stud spaces at west side of stairs. |
| | | 6. | Install steel support post at east end of basement. |
| | | 7. | Install security blocking at basement exterior door |

Comments: