

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20181667
Address: 2601 SW PRYOR RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
DEI-Sanitary Sewer - Vacuum	John DiMauro	Partial	Tuesday, November 27, 2018

Informational:

1

John DiMauro 11/27/2018 11:35 AM

The crew vacuum tested MH E-1
The gauge dropped from 10 to 9.5 during the 2.5 min test. Test Passed.

Vacuum test for MH G-3
The gauge dropped below the allowed limit in the 2.5 minute test.
Test Failed

Comments: