

Inspection Summary

Permit #: PRSITE20183647, Development - Site

PARAGON STAR

Address: 1401 NW VIEW HIGH DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DE - Grading/Excavation/Fill Inspection Informational	John Jackson	Partial	Thursday, April 18, 2019
1	Contractor Clarkson continued grading site area for contruction. Contractor work to reroute water from Line 300 to prepare to install Toe Wall & Wings.		

Comments: