

Inspection Summary

Permit #: PRSUBD20162865, Development - Subdivision
MONTICELLO 3RD PLAT

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DE - Street - Base Lift	Steve Robbins	Passed	Thursday, April 18, 2019
DE - Street - Wedge Lift	Steve Robbins	Passed	Thursday, April 18, 2019
DE - Street - Surface Course	Steve Robbins	Passed	Thursday, April 18, 2019
DE - Install Street and Stop Signs	Steve Robbins	Passed	Thursday, April 18, 2019
Informational			
1 All the street signs have been installed.			
DE - Curb - Compression Strength	Steve Robbins	Passed	Thursday, April 18, 2019
DE - Storm - Swales	Steve Robbins	Passed	Thursday, April 18, 2019

Informational

- 1 John Jackson, Steven Concrick and myself have been out and checked the swales and as-graded and it all appears to be in good standing.

DE - ESC -
(Vegetation/Ground Cover)
Informational

Steve Robbins

Partial

Thursday,
April 18, 2019

- 1 The contractor has installed hay and seed throughout the site, we allowed them to install hay because of a shortage of straw.

Comments:
