	1		
	inspectio	on Summary	
Permit #: PRSUBD20182996, OAKVIEW STORAG Address: 1410 NE DOUGLAS	E PHASE II		
	=	results noted below. Please of the control of the cover any work until	
Inspection Item: Inspection:	Inspector:	Outcome:	Date:
DE - Water Line - Hydrostati Test Informational	c Joe Starlin	Passed	Monday, April 22, 2019
	2019 3:50 PM The Be	eemer crew pressurized the w	rater line at 200psi for
Comments:			