

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20183161
Address: 3324 SW JESSIE LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mike Copeland	Failed	Thursday, April 25, 2019

Corrective Action Required:

1	Misc	1. EAST SIDE PURLIN OVER KITCHEN, INSTALL ADDITIONAL PURLIN LEG. 2. INSTALL BLOCKING TO PREVENT LVL OVER GREAT ROOM FROM LATERAL ROTATION
---	------	---

OKAY TO INSULATE

Comments: