

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20183842
Address: 104 SW MEADOWBROOK DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Jason McRoy	Failed	Friday, April 26, 2019

Corrective Action Required:

- | | | |
|---|------|--|
| 1 | Misc | 1. Install anchor at bottom plate east wall in garage at splice.
2. Install security blocking at rear entry door.
3. Fire block vertically at north wall in rec room at corner going into west bedroom.
4. Fire block vertically at northwest bedroom in northwest corner or close to.
5. Complete vertical fire blocking at east wall in northwest bedroom in basement. |
|---|------|--|

OK TO INSULATE

Comments: