

# Inspection Summary

Permit #: PRSITE20183647, Development - Site

PARAGON STAR

Address: 1401 NW VIEW HIGH DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DE - Storm - Outlet Structure		Partial	Friday, April 26, 2019

1

Informational

2 Contractor continued to construct Toe wall on Line 300 and encasement( for Kansas City Sanitary Pipe Line) throughout the week of 4/22/19 to 4/26/19. Conrete pour for encasement of sanitary pipeline began around 1:30 pm. Project picture were taken of progress.

Comments: