

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20183809
Address: 4521 SW NAUTILUS PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Jason McRoy	Partial	Monday, May 06, 2019

Corrective Action Required:

2	Misc	1. fire stop electrical penetrations at top plate above garage entry door. 2. where 4 studs were added to support steel beam in great rm. studs were notched for electrical. protect electrical wiring with plates from side to side.
---	------	--

OK TO INSULATE

Comments: