

Inspection Summary

Permit #: PRRES20184003, Building Permit - Residential

Address: 100 SW MEADOWBROOK DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
Driveway Inspection	Steve Robbins	Partial	Tuesday, May 07, 2019

Informational

- 1 The approach has been formed and the rock has been compacted. The curbs appear to be in good condition . They are ready to pour the concrete.

Comments: