CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRSUBD20184050 Address:

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
DE - Sanitary Sewer - Vacuum	John DiMauro	Passed	Wednesday, May 15, 2019
Informational:			
1 Misc	 On Site with the Redford crew to vacuum test the sanitary manholes for lines 3-A & 3-B Line 3-A: MH 3-A1 Is 11'ft deep and held at 10 with no drop for 2min and 30 seconds. Test Passed. MH 3-A2 is less than 10' ft deep and dropped from 10 to 9.5 in 2 minutes. Test Passed. MH 3-A3 is less than 10'ft deep and dropped from 10 to 9.5 in 2 minutes. Test Passed. Line 3-B: MH 3-B2 is 10' ft deep and held at 10 with no drop in 2 minutes. Test Passed. MH 3-B2 is 10'ft deep and held at 10 with no drop in 2 minutes. Test Passed. MH 3-B2 is 10'ft deep and held at 10 with no drop in 2 minutes. Test Passed. 		

MH 3-B4 is less than 10 ft deep and held at 10 for 2 minutes. Test Passed.

Comments: