

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20190280  
Address: 4418 SW AMETHYST DR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection:                               | Inspector:  | Outcome: | Date:                  |
|---|-------------|----------|------------------------|
| <b>All Rough Inspection - Residential</b> | Jason McRoy | Failed   | Thursday, May 16, 2019 |

Corrective Action Required:

|   |      |   |
|---|------|---|
| 1 | Misc | Strap top plates in master bedroom at girder truss behind fireplace.<br>Strap top plate at master bath above left side of vanity.<br>Fire block vertically all 2x4 to concrete walls in basement at 10 ' intervals.<br>Fire block dead space in southwest bed in basement at north wall |
|---|------|---|

**Comments:**