CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20172509

Address: 217 NW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Rated Assembly Inspection Mike Copeland Partial Friday, May 17, 2019

Corrective Action Required:

1 THE FOLLOWING pre rock-tub showers

AREAS ARE dryer boxes
APPROVED furnace rooms.

HAT CHANNEL LIDS TOP FLOOR APPROVED

Corrective Action Required:

2 LOWER LEVEL Corrective Action Required:

3 FIRST FLOOR RC

Corrective Action Required:

4 SECOND FLOOR RC-EXCEPT RM 305 AND HALL OUTSIDE 305

Comments: