

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20190046  
Address: 2033 NE BLUESTONE DR, LEES SUMMIT, MO 64064

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Khanh Nguyen	Failed	Thursday, May 30, 2019

Corrective Action Required:

1 Misc

FRAMING:

- Install trim and flashing above window
- Complete Install windows above slide door
- Fb the b-vent chase from roof; Fb fireplace space; Fb shower wall from roof; Fb wall from joist space at basement shared bathroom ; Fb at top of vertical Fireblock; Fb basement wall from soffit
- Nail great room ceiling beam hanger near I beam
- Support over notched bottom of valley rafter in garage
- Solidblock under garage I beam point load
- Support lvl beam at stair wall (shim gap)

MECHANICAL:

- Seal return air space below fireplace

**\*\*OK TO INSULATE**

**Comments:**

