CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20172509

Address: 217 NW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Rated Assembly Inspection Mark Harding Partial Tuesday, June 04, 2019

Corrective Action Required:

1 THE FOLLOWING pre rock-tub showers

AREAS ARE dryer boxes
APPROVED furnace rooms.

RC CHANNEL LIDS TOP FLOOR APPROVED

-TOP FLOOR UNITS APPROVED

-SOUTH STAIR TOWER

Corrective Action Required:

2 LOWER LEVEL RC channel lower level approved

Corrective Action Required:

3 FIRST FLOOR RC

LAUNDRY BOXES, TUBS AND SHOWERS APPROVED PRE ROCK

Corrective Action Required:

4 Misc CORRIDOR AND SOUTH GARAGE NEEDS ALL CEILING PENETRATIONS SEALED

FOR FLOOR CEILING ASSEMBLY

AREAS UNDER DECKS NEED INSPECTED WHEN READY

LOWER GARAGE AREAS (4)

Corrective Action Required:

5 SECOND FLOOR OK UNITS

Comments: