CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20183262 Address: 837 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Underground Electrical Inspection - Commercial		Inspector: John Borns	Outcome: Partial	Date:	
				Wednesday, June 05, 2019	
Partial Correctio	n:				
1 Misc		TWO 1-1/4" OUTSIDE CODUIT APPROVED 2 THREE 4" FROM (C) T TWO 1-1/4" + ONE 3 1-1/4" + TWO 3/4" FE 3/4" FROM (J) TO (K) 3/4" FROM (G) TO (M WITH ONE STUBBED ONE 3/4" FROM (G) TO (P); TWO 1-1/4" + ON	DK TO COVER WHEN READY TRENCHED ELECTRICAL CONDUIT AT: THREE 4" + WO 1-1/4" OUTSIDE WEST WALL OF BLDG 1 LEFT WING; SAME CLUSTER OF CODUIT APPROVED 140 FEET SOUTH TO 90 EAST TO (C); + 50' EAST TO (E); THREE 4" FROM (C) TO (D); THREE 4" + TWO 1-1/4" FROM (E) TO (F); THREE 4" + WO 1-1/4" + ONE 3/4" FROM (F) TO (G); ONE 1-1/4" FROM (H) TO (I); ONE -1/4" + TWO 3/4" FROM (I) TO (J); ONE 3/4" STUBBED EAST FROM (J); TWO D/4" FROM (J) TO (K); TWO 3/4" FROM (K) TO (L); THREE 4" + TWO 1-1/4" + ONE B/4" FROM (G) TO (M); THREE 4" + TWO 1-1/4" + TWO 3/4" FROM (M) TO (N) WITH ONE STUBBED WEST AT (M) FOR SITE LIGHTING; TWO 4" + TWO 1-1/4" + ONE 3/4" FROM (G) TO (M); THREE 4" + TWO 1-1/4" + ONE 3/4" FROM (N) TO P); TWO 1-1/4" + ONE 3/4" FROM (Q) TO (S); ONE 3/4" FROM (Q) TO (R); ONE B/4" FROM (T) TO (U);		
		BLDG 1 - FOUR 4" + 0		SFORMER LOCATION TO BLDG: RY 4" FROM (V) TO 24' EAST @ E 4" @ N END;	
		LOCATIONS (X) REFE	RENCED ARE NOTED ON I	INSPECTOR'S COPY OF SITE	

3/4" CONDUIT AT CONSTRUCTION ENTRANCE APPROVED.

3/4" CONDUIT 110 FEET FROM SE CORNER OF THE BUILDING; REMAINDER OF RUN TO VAULT AT (W);

Comments: