

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20190046
Address: 2033 NE BLUESTONE DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Khanh Nguyen	Failed	Wednesday, June 05, 2019

Corrective Action Required:

1	Misc	-Fb the b-vent chase from roof **need min 1" clearance from b-vent to OSB Fb basement wall from soffit **get some insulation and pack in the opening at wall-to-furdown intersection at rear basement bedroom and at rear wall of basement recreation rm -Support lvl beam at stair wall (shim gap) **protect the electrical wire below **OK TO INSULATE
---	------	--

Comments: