

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20190421
Address: 4414 SW AMETHYST DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Jason McRoy	Failed	Friday, June 07, 2019

Corrective Action Required:

1	Misc	Strap top plates on garage side of double wall left of triple lvl. Fire block fir down southwest corner of garage. Framing left of entry door to be 2x6 full height redo framing and support beam for front porch. Attach bath fan front bath 2nd fl.
---	------	--

Comments: