

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20190043
Address: 1912 NE CATALINA AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Khanh Nguyen	Failed	Monday, June 10, 2019

Corrective Action Required:

1 Misc

FRAMING:

- At rear wall, break header between windows with a full height king stud per plan; or strap
- Nail lvl hanger above rear dining
- Full support underneath lvl point load. Look at great room/bedroom wall adjacent to return air

ELECTRICAL:

- Overfilled 2-gang box left of range

MECHANICAL:

- Provide combustion air openings for water heater

****OK TO INSULATE**

Comments:

