

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20190346  
Address: 4508 SW NAUTILUS PL, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Brandon Kalwei	Failed	Wednesday, June 12, 2019

Corrective Action Required:

1	Misc	-Fire block dead space west wall main level at top plate where plumbing comes through -fire block west wall top plate where HVAC comes through -fire block dead space at top plate space in between garage and where oven will be -fire block dead space at top plate east side, next to garage wall -fire block both dead spaces, left and right of garage door entrance -anchor down posts in basement -complete water line under stairs in basement -solid blocking in between joists on main floor above stove/fridge area -two spots of cut floor joists in basement, needs to be fixed -fire block stair wall leading to basement at joists height -missing 2 - 2x4s at right side of stairs leading down to basement -support plumbing in garage every 4'
---	------	---

Comments: