CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRSUBD20190968Address:701 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | | Inspector: | Outcome: | Date: |
|--|------|---|--|-----------------------|
| DE - Water Line - Construction Inspection | | Joe Starlin | Partial | Friday, June 14, 2019 |
| Informational: | | | | |
| 3 | Misc | 6-13-19 9:00am They have placed 120' of waterline with rock and tracer wire. Tracer tape is going in with the back fill. They have stoped placing waterline until locates are made. A total of 240' of waterline was place with tracer wire and rock. Tracer tape and backfill followed. | | |
| Informational: | | | | |
| 2 | | 6-12-19 11:30am approximately 130' of waterline has been laid with tracer wire. 3:24pm They have placed approximately 340 feet of line so far along with rock wire and tape. There is a storm moving in so they are shutting down for the day. They need to call for some locates to move forward. | | |
| Informational: | | | | |
| 1 | | and covered with rock. Th | nave placed five sticks of wa ere lead man Andrew has b below finished grade. 3:30 | een informed to put |

Comments: