

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20172507
Address: 213 NW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Mark Harding	Failed	Tuesday, July 16, 2019

Corrective Action Required:

1	Misc	108 - studs at laundry, pre rock caulk pvc, Dwv. Turn out clean outs. 106- tun out clean outs clean outs . Tie top plates bedroom north wall. Broken outlet box seats wall bedroom. 208,206-stud under sprinkler pipe north wall. 207- prerock.ok 205- joist hanger joist into lvl's. 306- strap top plates north wall at header for porch, stud under header also. 308, 307.,305ok. North section-301,302- 303- support SE cable in attic. 304- stud under header for stair wall. Stud for sprinkler pipe south wall kit. 201-caulk water line north wall. Complete sprinkler pipe through top plate and wall.203 fix elect to switch box west exterior door. 202-electrical rear east door. 204-strap top plates bedroom south exterior wall. 101-104 strap top plates porch wall.
---	------	--

Comments:

