

Inspection Summary

Permit #: PRSUBD20162865, Development - Subdivision
MONTICELLO 3RD PLAT

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DE - Water Line - Construction Inspection Informational	John Jackson	Partial	Wednesday, July 17, 2019
1	Water sample had to be retaken because of a valve was closed on Jamestown Drive and stopped the flow of water to water main on a dead end cul de sac of NE Goshen Court . The first sample was taken on 7/16/19 7:00AM and the second was taken 7/17/19 8:30 AM.		

Comments: