

Inspection Summary

Permit #: PRSITE20191865, Development - Site
REECE NICHOLS SITE DEVELOPMENT
Address: 222 SW MAIN ST, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DE - Storm - Pipe	Joe Starlin	Partial	Thursday, July 18, 2019

Informational

1 Joe Starlin 07/18/2019 7:24 AM On 7-17-19 at 2:30pm The crew installed storm pipe on the north side of the site and backfilled with type 5 in 8" lifts.

Comments: