

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20172507
Address: 213 NW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Mark Harding	Failed	Friday, July 19, 2019

Corrective Action Required:

1	Misc	108 - studs at laundry,Dwv. Turn out clean outs. 106- tun out clean outs clean outs . 208,206-stud under sprinkler pipe north wall. 207- prerock.ok 205- joist hanger joist into lvl's. 306-308, 307.,305ok. North section-304- stud under header for stair wall. Stud for sprinkler pipe south wall kit. 201-caulk water line north wall. Complete sprinkler pipe through top plate and wall.
---	------	--

Comments: