CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRSUBD20181667 Address: 2601 SW PRYOR RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
DE - Water Line - Const Inspection	truction John DiMauro	Partial	Wednesday, July 24, 2019	
Informational:				
1 Misc	inspected approxima 6+52.37 to about 8+50	The Redford Construction crew is on site installing the Public water main. I inspected approximately 200' ft of the line they have laid from station 6+52.37 to about 8+50. The crew installed the 90 degree bend at the road crossing and the gate valve at station 6+62.37 Photos are attached.		
Informational:				
2 Misc Informational:	The Redford crew co	ntinued the install to app	proximately station 12+10.42	
3 Misc			e A install. Photos are the n for further inspection today.	
Informational:				
4 Misc		e plans and the materials	alling water line C. The install used are correct. I will return	
Informational:				
5 Misc			er line C today. I verified that nat the materials used meet the	
		tinuing the install of pub m approx station 15+10.4	lic water line A. The crew has 0 to 17+34.29	

I verified correct materials used and that the install matches the plans and meets the city standards.

Photos are attached to the permit.

Comments: