

Inspection Summary

Permit #: PRSUBD20191897, Development - Subdivision

Pergola Park 4th Plat

Address: 3200 SW PERGOLA PARK DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DE - Sanitary Sewer Construction Inspection Informational	Steve Robbins	Partial	Friday, July 26, 2019
1	The contractor has installed MHSteve Robbins 07/26/2019 4:01 PM b-1 and b-2 and was working toward b-3. They said they will do compaction tests on the road crossings at the end and they would dig them up all the way across and do them in lifts.		

Comments: