

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20190111
Address: 4829 NE JAMESTOWN DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Jason McRoy	Failed	Tuesday, July 30, 2019

Corrective Action Required:

1	Misc	Fire block top plate at mud room double wall. Fire block heat chase from closet and joist space. 1st fl. Install anchors at southeast sill plate in garage. Repair hole in floor sheathing at front entry. Harder joist and install hangers above water heater location. OK TO INSULATE
---	------	--

Comments: