CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20191897

Address: 3200 SW PERGOLA PARK DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

DE - Sanitary Sewer Steve Robbins Partial Tuesday, July 30, 2019

Construction Inspection

Informational:

1 Misc The contractor has installed MHSteve Robbins 07/26/2019 4:01 PM b-1 and

b-2 and was working toward b-3. They said they will do compaction tests on the road crossings at the end and they would dig them up all the way across

and do them in lifts.

Informational:

2 Misc The b - line has all been installed. MH b-3 was installed yesterday . All the

service lines has been installed, the tracer wire has been installed with anodes and the trench checks have been installed. They wyes have been installed and are 4 ft. apart. The contractor is going to dig up the road crossings and do compaction tests later. He undrstands he has to do lifts and

not pot-hole them. Steve Robbins 07/30/2019 8:31 AM

Comments: