

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20191897
Address: 3200 SW PERGOLA PARK DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
DE - Sanitary - Material Verification	Ronald Paynter	Passed	Tuesday, August 06, 2019

Informational:
1 Misc 8 inch SDR 26 sanitary pipe manufactured by North American Pipe Company.
4 inch SDR 26 laterals. 8 inch Ductile C 50 manufactured by McWane Ductile.
Manholes were manufactured by Barbour. They have ML-13-NCR steps with
1502 A sewer lids. RP 7-24-19

Comments: