

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20190832  
Address: 4409 SW NAUTILUS PL, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Jason McRoy	Failed	Tuesday, August 06, 2019

Corrective Action Required:

1	Misc	Fire block above great room entry from mudroom above doorway and on both sides. Fir out beam of in basement. Fire block dead space at southeast firred out wall in basement. Fire block vertically at northeast corner of basement in closet. Secure wiring within 12" of panel. OK TO INSULATE
---	------	--

Comments: