

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20183802
Address: 4528 SW NAUTILUS PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Jason McRoy	Failed	Tuesday, August 06, 2019

Corrective Action Required:

1	Misc	Strap top plate at gas line penetration in laundry room. Fire block above fireplace in great room. Fire block above oven location. Protect plumbing at back side of master bath vanity. Protect plumbing left side of makeup counter top and bottom. Complete plumbing , drain , water supply, protect plumbing top bottom middle of master bath shower. Install stud shoes at middle bath plumbing in basement. Install bath fan in east bath in basement. Set ground screw at main panel. Repair hole in siding and ledger board missed bore under deck.
---	------	---

plumber was still working on gas line at time of inspection. no gauge on gas line.

Comments: