

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20190489
Address: 4422 SW AMETHYST DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Brandon Kalwei	Failed	Monday, August 12, 2019

Corrective Action Required:

1	Misc	- Fire block duct work at top plate in garage, left of door way -fire block vent pipe on second floor at top plate -strap top plate in west bedroom second floor, north and south side of room *ok to insulate
---	------	---

Comments: