

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20191897
Address: 3200 SW PERGOLA PARK DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
DE - Sanitary Sewer Construction Inspection	Ronald Paynter	Partial	Wednesday, August 14, 2019

Informational:

1 Misc

Walters Construction set sanitary laterals for lots 99 and 109. Wyes were used for connecting the laterals to the sanitary main. Trench checks were poured for the laterals. Still need compaction test done on road crossings.
RP 8-13-19

Comments: