Inspection Summary			
Permit #: PRSITE20183577, D INTERNATIONAL BL Address: 2320 NE INDEPENDI	ILDERS AND CONSULTA	•	
This work has been inspected once all corrective actions ha	•		•
Inspection Item: Inspection:	Inspector:	Outcome:	Date:
DE - Curb - Proof Roll	John Jackson	Passed	Thursday, August 22 2019
Informational			
inspection was don		tractor will pass on paper pection grouting areas tha	
inspection was don	e and curbs passed insp 08/22/2019 4:31 PM		t had been done by Thursday, August 22
inspection was don hand. John Jackson DE - Curb New/Replacement Informational	e and curbs passed insposed in	pection grouting areas tha	t had been done by Thursday, August 22 2019
inspection was don hand. John Jackson DE - Curb New/Replacement Informational	e and curbs passed insposed in	pection grouting areas that	t had been done by Thursday, August 22 2019