

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20172513  
Address: 229 NW KESSLER DR, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Commercial</b>	Mark Harding	Failed	Monday, August 26, 2019

Corrective Action Required:

1	Misc	<ul style="list-style-type: none"><li>*Garage #7 rock top of plumbing chase open gaps ,5 from the west.</li><li>*106- strap top plates cut for sprinkler. NOT SEALED AT TOP PLATE</li><li>-Draft stop penetrations 1000 sq ft.</li><li>*108- pre rock nail pattern INCOMPLETE collar cut in half, hole on lower rock between hallways.</li><li>206 collar cut in 1/2.</li><li>*207-dryer boxes in corridor walls 205,207..</li><li>*support flex duct i attic with 2" material room 207 main duct in great room.</li><li>COMMON AREAS:*3000 sq ft draft stip atic.</li><li>**no rock furnace room box out 2nd floor east corridor. HEAT DUCT REMOVED LYING ON THE FLOOR.</li><li>**201-no dryer boxes inwalls. INCOMPLETE</li><li>**203-no dryer boxes in wallsINCOMPLETE</li><li>*PREROCKROOMS201,203,205,207.OK(EXECPT DRYER BOX 201,203)</li></ul>
---	------	---

Comments: