CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20183262 Address: 837 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Underground Electrical Inspection - Commercial	John Borns	Partial	Wednesday, August 28, 2019
Partial Correction:			
1 Misc	TWO 1-1/4" TO (A); SA 90 EAST TO (C); + 50' E 1-1/4" FROM (E) TO (F) ONE 1-1/4" FROM (E) TO (F) ONE 1-1/4" FROM (H) T STUBBED EAST FROM (THREE 4" + TWO 1-1/4 TWO 3/4" FROM (M) T LIGHTING; TWO 4" + T' TWO 1-1/4" + ONE 3/4 (S); ONE 3/4" FROM (C) CONSTRUCTION ENTR/ CORNER OF THE BUILD TWO 1-1/4" FROM (M) 4" + ONE 3" FROM (Z) TO (BB); ONE 3/4" (FRO THREE 4" + TWO 1-1/4 1-1/4" + ONE 3/4" FRO (JJ) TO (KK); THREE 4" - 30' EAST; THREE 4" + T	AST TO (E); THREE 4" FROM (; THREE 4" + TWO 1-1/4" + C TO (I); ONE 1-1/4" + TWO 3/4 (J); TWO 3/4" FROM (J) TO (K " + ONE 3/4" FROM (G) TO (N O (N) WITH ONE STUBBED W WO 1-1/4" + ONE 3/4" FROM WO 1-1/4" + ONE 3/4" FROM WO 1-1/4" + ONE 3/4" FROM (N) TO (P); TWO 1-1, the transformer of the transformer (N) TO (R); ONE 3/4" FROM (T) ANCE APPROVED; 3/4" CONE (TO (R); THREE 4" + THREE 1- TO (AA); ONE 3/4" AT ISLANE (TO (AA); TO (CC); FOUR 4" + OI " FROM (EE) TO (FF); TWO 3/	PROVED 140 FEET SOUTH TO (C) TO (D); THREE 4" + TWO ONE 3/4" FROM (F) TO (G); 4" FROM (I) TO (J); ONE 3/4" (I); TWO 3/4" FROM (K) TO (L); (I); TWO 3/4" FROM (K) TO (L); (I); THREE 4" + TWO 1-1/4" + VEST AT (M) FOR SITE I (G) TO (M); THREE 4" + (G) TO (M); THREE 4" + (4" + ONE 3/4" FROM (Q) TO TO (U); 3/4" CONDUIT AT OUIT 110 FEET FROM SE O VAULT AT (W); THREE 4" + -1/4" FROM (X) TO (Y); FOUR O @ (W); ONE 3/4" FROM (X) NE 3" FROM (CC) TO (DD); (4" FROM (GG) TO (HH); ONE THREE 4" + ONE 1-1/4" FROM ROM (LL) TO (MM) - THEN M (LL) TO (NN) 60' SOUTH;

REMAINDER OF CONDUITS FROM E/SE CONVERGING ON LOCATION OF BOX TO BE INSTALLED AT (II); FOUR 4" + ONE 3" FROM XFMR LOCATION TO W END OF BLDG 4; THREE 4" FROM E END OF BLDG 4 NORTH 35',THEN S 15' TO (OO); FROM MONUMENT SIGN AT NORTH ENTRANCE TWO 3/4" TO 30' SE & TWO 3/4" TO 30' SW; FOUR 4" + ONE 3" FROM (OO) TO (PP) & SECONDARY CONDUITS AT (PP); THREE 4" + TWO 1-1/4" FROM (A) TO 24' N; FOUR 4" + ON 3" FROM NW CORNER OF LEFT WING OF BLDG 1 TO XFRMR LOCATION; THREE 4" + TWO 1-1/4" AT & N 25' OF (QQ); **ALL COMPLETE AND CONNECTED TO 30' N OF (QQ);**

SECONDARY SERVICE CONDUITS FROM TRANSFORMER LOCATION TO BLDG: BLDG 1 - FOUR 4" + ONE 3"; THREE SECONDARY 4" FROM (V) TO 24' EAST @ BLDG 1; BLDG 2 - FOUR 4" @ SO END + THREE 4" @ N END;

LOCATIONS (X) REFERENCED ARE NOTED ON INSPECTOR'S COPY OF SITE ELECTRICAL PLAN.

EAST SIDE MAIN BUILDING: 3 4" SECONDARY 1 4" PRIMARY APPROVED

BUILDING 5 SECONDARY CONDUITS APPROVED

Comments: