

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20183155
Address: 3329 SW JESSIE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Brandon Kalwei	Failed	Thursday, August 29, 2019

Corrective Action Required:

1	Misc	-Nail corner studs per code master bedroom -box up electrical in master bedroom in corner nook near top plate -protect waterlines at bottom plate master shower -support cold water line midway master shower -box up electrical wire left of master bath sinks -box up vanity lights electrical wires in front bathroom -stud shoe needed for laundry drain pipe and stud to the left of it - box up electrical wires in basement main room east wall -Properly fire block double walls in basement, if using insulation it needs to be tight -Support vent pipe in basement mid way in bathroom -Fire block joists space in dead space behind basement shower -Support waterline south side foundation wall mid way -Box up electrical wires for vanity in basement west wall
---	------	---

Comments: