

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRSUBD20191897  
Address: 3200 SW PERGOLA PARK DR, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>DE - Sanitary Sewer - Air Test</b>	Ronald Paynter	Passed	Wednesday, September 04, 2019

Informational:  
1 Misc Dustin from Walters Excavating performed the air test on the following sanitary lines. The gauge was calibrated within the last year. MHC1 to MHA6 and MHC2 to MHC1 passed their test. RP 9-4-19

**Comments:**