

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRSUBD20191897  
Address: 3200 SW PERGOLA PARK DR, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>DE - Sanitary Sewer - Vacuum</b>	Ronald Paynter	Passed	Wednesday, September 04, 2019

Informational:  
1 Misc Dustin from Walters Excavating performed the vacuum test on the sanitary line. Gauge was calibrated within the last year. MHC1 and MHC2 passed their vacuum tests. RP 9-4-19

**Comments:**