Inspection Summary			
Permit #: PRSITE20174026 Lee's Summit Su Address: 2801 NE INDEPE	•	IT, MO 64064	
		sults noted below. Please ca not cover any work until a	
nspection Item: Inspection:	Inspector:	Outcome:	Date:
DE - Street - Base Lift	John Jackson	Partial	Friday, Septembe 06, 2019
			1.1.0
Corrective Action Required Contractor layer	d base level asphalt on par	king lot 9/3/19 and finish 9	/4/19. As per plans.