## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRSUBD20181667

Address: 2601 SW PRYOR RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

**DE - Water Line - Construction** John DiMauro Partial Monday, September

Inspection 09, 2019

Informational:

1 Misc The Redford Construction crew is on site installing the Public water main. I

inspected approximately 200' ft of the line they have laid from station 6+52.37 to about 8+50. The crew installed the 90 degree bend at the road

crossing and the gate valve at station 6+62.37

Photos are attached.

Informational:

2 Misc The Redford crew continued the install to approximately station 12+10.42

Informational:

3 Misc The Redford Crew is continuing the Water Line A install. Photos are the

current progress are attached and I will return for further inspection today.

Informational:

4 Misc The Redford Construction crew is on site installing water line C. The install

appears to match the plans and the materials used are correct. I will return

for further inspections this afternoon.

Informational:

5 Misc The Redford Construction crew installed water line C today. I verified that

the install matched the approved plans and that the materials used meet the

city standards.

The crew is now Continuing the install of public water line A. The crew has

the line installed from approx station 15+10.40 to 17+34.29

I verified correct materials used and that the install matches the plans and meets the city standards.

Photos are attached to the permit.

Informational:

6 Misc The Redford crew is working on the water line A install. The crew has the line

ran from approx 17+34.29 to station 19+19.27

I inspected the Thrust blocks and restraints poured yesterday on water lines

A & C. The install appears to meet the city standards.

Photos are attached to the permit.

Informational:

7 Misc The Redford crew moved over from the off site to work on the on site creek

crossing of the waterline. The are preparing the encasement pipe at this

time.

Informational:

8 Misc The Redford Construction crew is working on the creek crossing section of

the water line. The crew was breaking rock today and plans to install the line

tomorrow.

## **Comments:**