

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20191897
Address: 3200 SW PERGOLA PARK DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
DE - Sanitary Sewer - Mandrel	Ronald Paynter	Passed	Wednesday, September 11, 2019

Informational:

1 Misc

Dylan from Walters Excavating performed the mandrel test. They used a 7.37 inch mandrel for the 8 inch sanitary line. The mandrel passed successfully through the following manholes. B3 to B2, B2 to B1, B1 to existing A4, C2 to C1, and C1 to existing A6. RP 9-11-19

Comments: