CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20191460 Address: 1160 NE DOUGLAS ST, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Above Ceiling Inspection		Inspector: John Borns	Outcome: Partial	Date: Thursday, September 12, 2019
1	Misc	OK TO COVER WHEN READY GWB CEILING / SOFFIT / BULKHEAD FRAMING + ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES: SOFFITS AT THE FOUR CORNERS OF CORRIDOR; SOFFITS AT VESTIBULE;		
Partial Co	prrection:			
2	Misc	OK TO COVER WHEN READY ACT CEILING FRAMING + ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES: CORRIDORS; ALL ROOMS EXCEPT COLOR PROCESSING, RESTROOMS, UTILITY CLOSET, AND 123		
Correctiv	e Action Required:			
4	Misc	REMOVE REMAININ <u>VERIFICATION.</u>	G TEMPORARY ELECTRICA	L WIRING. <u>LEAVE OUT TILES FOR</u>

Comments: