	Inchastics	Cummany	
	Inspection	Summary	
Permit #: PRRES20190046	5, Building Permit - Residen	itial	
Address: 2033 NE BLUEST	ONE DR, LEES SUMMIT, M	O 64064	
This work has been inspe	cted and the inspection res	sults noted below. Please ca	all for re-inspection
once all corrective actions	· · · · · · · · · · · · · · · · · · ·	not cover any work until a	
once all corrective actions nspection Item:	· · · · · · · · · · · · · · · · · · ·		
nspection:	s have been completed. Do	not cover any work until a	pproved.
nspection Item: Inspection: Driveway Inspection  nformational	s have been completed. Do	o not cover any work until a  Outcome:	<b>Date:</b> Thursday, September