

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20172515
Address: 225 NW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Mark Harding	Failed	Tuesday, October 01, 2019

Corrective Action Required:

1	Misc	2nd floor 302 Screws in, pre-rock hurricane tie 301-truss hangers back door , hurricane over porch. Tie on girter truss bedroom. Screw pattern on peer rock. Corridor north stairs hanger 2x4 ceiling joist to truss. 304- screws on pre rock. 303-ok 306-plumbing nail guard bottom plate bedroom closet. Seal gap in pre-rock 305-puddly pad kitchen wall. Seal gaps on pre-rock. Hurricane tie on bedroom truss girter. Corridor north ceiling joist hangers . Terminate exit light in box over north stairs. Pre-rock hallway north end screw pattern. 308-pre rock gaps , screw pattern. Truss hangers. 307-truss hangers , ties on girter truss bedroom. Pre-rock ok 1st floor- 207-electrical to porch outlet box deck not installed. Gap in pre-rock 208-pre rock ok Corridor hvac north end pre rock. 205- prerock 206-ok
---	------	--

203-

204-

202- south wall at ac line set install stud for cut in plates.

Terminate elect over south stairs 1st floor.

Support DWV north garage #2

Comments: