

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20191430
Address: 4425 SW NAUTILUS PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Steve Quaid	Failed	Friday, October 11, 2019

Corrective Action Required:

1	Misc	** Draft stop has not been done throughout the house ** Main floor bathroom does not have an exhaust vent ** Flex room has wall space over 24" under window without an outlet ** North west upstairs bedroom is missing wire protection in the corner ** Windows at master bath tub need to be safety glass ** Missing joist hanger under porch
---	------	--

Comments: