CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20190043

Address: 1912 NE CATALINA AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Occupancy Inspection - Codes Khanh Nguyen Failed Monday, October 14,

Residential 2019

Corrective Action Required:

1 Misc -Submit approved as-graded plot plan

-Sewer tracer box and wire

-Seal exterior lights

-Pendant light not allowed within tub space -Install cover plate for sump pump receptacle

-Locate and make accessible the sewer clean out and ufer grounding

connection

Comments: