



1100 W Cambridge Circle Drive, Suite 700  
Kansas City, Kansas 66103  
913.627.9040

## DAILY FIELD REPORT

CLIENT: Streets of West Pryor, LLC  
3501 West 147th Street  
Leawood, Kansas 66224

PROJECT: Streets of West Pryor  
Lee's Summit, Missouri

ATTN: Dave Olson

DATE: 9/18/19

WEATHER: Sunny

CFS  
PERSONNEL: M. Simpson

TEMPERATURE: 80-90

REPORT #: 19-1066-dr- 70

---

### TYPE OF SERVICE BEING PERFORMED

**SOILS** COMPACTION MONITORING

**DEVIATION FOUND: NO**

**SOILS** COMPACTION TESTING

**DEVIATION CORRECTED:**

**ORIGINAL DEVIATION DATE:**

---

### WORK ACCOMPLISHED THIS DATE:

- Monitored placement and compaction of fill for
  1. Lot #8 observed rock removal for storm sewer line J and B (see reference diagram #1).
  2. Observed the 48" HDPE line A-2, 120 linear feet (elevation -9' to finish grade) adequate compaction was observed.
  3. Observed the 48" HDPE from A-2 to B-2, 100 linear feet (elevation -9' to finish grade) adequate compaction was observed.
  4. Compaction tests were taken for the 4" electrical conduit that crosses at Lowenstein drive, approximately 15' north of structure D-3.
- Field compaction tests performed and fill found to be in compliance with plans and specifications. Test results attached.