



1100 W Cambridge Circle Drive, Suite 700
Kansas City, Kansas 66103
913.627.9040

DAILY FIELD REPORT

CLIENT: Streets of West Pryor, LLC
3501 West 147th Street
Leawood, Kansas 66224

PROJECT: Streets of West Pryor
Lee's Summit, Missouri

ATTN: Dave Olson

DATE: 10/2/19

WEATHER: Sunny

CFS
PERSONNEL: M. Simpson

TEMPERATURE: 70-85

REPORT #: 19-1066-dr- 77

TYPE OF SERVICE BEING PERFORMED

SOILS COMPACTION MONITORING

DEVIATION FOUND: NO

SOILS COMPACTION TESTING

DEVIATION CORRECTED:

ORIGINAL DEVIATION DATE:

WORK ACCOMPLISHED THIS DATE:

- Monitored placement and compaction of fill for
 - 1.) Retaining wall - J from station 0+00 to 0 + 33 (elevation 984.33), all work completed per job site specifications.
 - 2.) Observed the 48" HDPE from A-4 to A-5, 80 linear feet (elevation -9' to finish grade) adequate compaction was observed.
- Monitored placement and compaction of fill for Two road crossings on Lowenstein drive were retested for compaction.
- The compaction test were for the 8" sanitary sewer crossings of the road at station 250 + 50 and station 37 + 00.
Compaction report attached
- Fill found to be in compliance with plans and specifications.